

Date: June 8, 1993

Subject: **Changes to 25 Series Steering Control Unit (-002 & -003 Revision Levels)**
Changes to 40 Series Steering Control Unit (-002 Revision Level)

25 Series Steering Control Unit - 002 Revision Level

Effective February 1993, the housing for the 25 Series Steering Control Unit was changed from gray iron to ductile iron. This is a product improvement change to increase the pressure capability of the steering unit.

25 Series Steering Control Unit - 003 Revision Level
40 Series Steering Control Unit - 002 Revision Level

Effective August 1, 1993, the three piece shaft seal arrangement (9092-033 seal, 14400 back-up ring, 250001- 121 o-ring) is replaced with a new one piece seal (9233-001). The new one piece seal is completely interchangeable with the old three piece seal arrangement. A new seal kit (64468-000) has been created to service both the 25 & 40 series steering units. This new seal (64468-000) kit will service all revision levels (-001, -002, -003). The old (64429) seal kit is now obsolete. This is a product improvement change to improve the sealing of the shaft.

Willard Bennett
Technical Services Manager



Powering Business Worldwide

Eaton
Hydraulics Group USA
14615 Lone Oak Road
Eden Prairie, MN 55344
USA
Tel: 952-937-9800
Fax: 952-294-7722
www.eaton.com/hydraulics

Eaton
Hydraulics Group Europe
Route de la Longeraie 7
1110 Morges
Switzerland
Tel: +41 (0) 21 811 4600
Fax: +41 (0) 21 811 4601

Eaton
Hydraulic Group Asia Pacific
11th Floor Hong Kong New
World Tower
300 Huaihai Zhong Road
Shanghai 200021
China
Tel: 86-21-6387-9988
Fax: 86-21-6335-3912

© 2011 Eaton Corporation
All Rights Reserved
Printed in USA
Document No. C-STCU-TB002-E
Supersedes 00-SB93061
July 2011



Powering Business Worldwide